

01807.000906.



Cofe \$
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
FRANCOIS THOUMY et al.)	Examiner: K. Tran
Appl. No.: 09/450,716)	Group Art Unit: 2637
Filed: November 30, 1999)	
For: DEVICE AND METHOD FOR)	
THE DYNAMIC ALLOCATION)	
OF FREQUENCIES FOR)	
MULTICARRIER MODULATION)	
SYSTEMS)	
U.S. Patent No.: 7,039,120 B1)	November 21, 2006
Issued: May 2, 2006)	

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Certificate
NOV 28 2006
of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/24/2006 RFEKADU2 00000068 7039120


01 FC:1811

100.00 0P

NOV 28 2006

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,



John D. Magluyan
Attorney for Patentees
Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 121282v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 1 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE:

(30) **Foreign Application Priority Data**, "Jan. 29, 1999 (FR)...99 0134" should read -- Jan. 29, 1999 (FR)...99 01034 --.

COLUMN 1:

Line 21, "to" should read -- too --.

COLUMN 2:

Line 20, "transmission)." should read -- transmission. --.

COLUMN 3:

Line 49, "stream" should read -- streams --.

COLUMN 4:

Line 57, "coding," should read -- coding, and --.

COLUMN 5:

Line 57, "of" should read -- of: --.

COLUMN 7:

Line 18, "data)," should read -- data), and --.

COLUMN 8:

Line 10, "involving" should read -- involving: --;

Line 25, "signal;" should read -- signal; and --;

Line 34, "radiofre-" should read -- radio fre- --;

Line 51, "rate;" should read -- rate; and --; and

Line 57, "radiofrequency" should read -- radio frequency --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 2 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13:

Line 42, "it is" should read -- are --.

COLUMN 14:

Line 50, "Clearly that" should read -- Clearly, --.

COLUMN 17:

Line 14, "simplifies" should be deleted; and

Line 21, "radiofrequency" should read -- radio frequency --.

COLUMN 19:

Line 3, "Time=[[t=]] t₁" should read -- Time=t₁ -- and

"Time=[[t=]] t₂," should read -- Time=t₂, --.

COLUMN 20:

Line 13, "embodiment the" should read -- embodiment of the --;

Line 35, "accordance" should read -- according --;

Line 60, "created" should read -- created: --; and

Line 61, ":" should be deleted.

COLUMN 21:

Lines 26 and 35, "in" should read -- of --; and

Line 46, "comprises" should read -- comprises: --.

COLUMN 23:

Line 7, "a" (second occurrence) should read -- as --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 3 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 28:

Line 46, "FIG." should read -- (FIG. --.

COLUMN 29:

Line 47, "be" should read -- the --.

COLUMN 31:

Line 45, "the 501." should read -- the 501 --.

COLUMN 35:

Line 12, "with" should read -- which --.

COLUMN 36:

Line 17, "solutions" should read -- solutions: --.

COLUMN 37:

Line 23, "(eg" should read -- (e.g., --.

COLUMN 38:

Line 31, "changed. invention" should read -- changed. ¶ The scope of the present invention is not limited to the details of the forms of embodiment discussed above by way of example but extends, on the contrary, to changes within the grasp of a man of the art. It is clear, for example, that the invention --; and

Line 56, "sub-carriers" should read -- sub-carrier --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 4 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 39:

Line 9, "said" should be deleted;

Line 29, "comprising" should read -- comprising: --; and

Line 61, "signals," should read -- signals; --.

COLUMN 40:

Line 4, "read," should read -- read; --;

Line 7, "table," should read -- table; --;

Line 10, "signal," should read -- signal; --;

Line 12, "insetting" should read -- inserting --;

Line 13, "means," should read -- means; --;

Line 19, "means," should read -- means; and --;

Line 22, "wherein data" should read -- wherein said data --;

Line 53, "Method" should read -- A method --; and

Line 65, "important;" should read -- important; and --.

COLUMN 41:

Line 3, "important, transmitting" should read -- important; ¶ transmitting --;

Line 4, "radiofrequency" should read -- radio frequency --;

Line 6, "Method" should read -- A method --;

Line 9, "radiofrequency" should read -- radio frequency -- and "receiver," should read -- receiver; --;

Line 11, "data," should read -- data; --;

Line 21, "comprising" should read -- comprising: --;

Line 24, "radiofrequency" should read -- radio frequency --;

Line 25, "multi carrier" should read -- multi-carrier --;

Line 28, "bit" should read -- data --;

Line 29, "modulator," should read -- modulator; --; and

Line 46, "image" should read -- an image --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

MAY 28 2006



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 5 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 42:

Line 1, "radiofrequency" should read -- radio frequency --;

Line 5, "rate," should read -- rate; --;

Line 6, "demodulator," should read -- demodulator; --;

Line 23, "radio" should be deleted; and

Line 44, "radio" should read -- the --.

COLUMN 43:

Line 6, "claim 46" should read -- claim 46, --;

Line 11, "channel," should read -- channel; and --; and

Line 44, "slip" should read -- step --.

COLUMN 44:

Lines 1, 7 and 30, "Method" should read -- A method --;

Line 3, "comprising," should read -- comprising --;

Line 34, "allocated" should be deleted;

Line 46, "wherein receiving" should read -- wherein the receiving --; and

Line 50, "are selecting" should read -- are selected in said selecting --.

COLUMN 45:

Line 3, "claim 75" should read -- claim 75, --;

Line 30, "channel," should read -- channel; --; and

Line 57, "channel," should read -- channel; and --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 6 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 46:

Line 31, "information," should read -- information; --;

Line 35, "acceptable" should read -- an acceptable --;

Line 54, "selected" should read -- selecting --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 1 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE:

(30) **Foreign Application Priority Data**, "Jan. 29, 1999 (FR)...99 0134" should read -- Jan. 29, 1999 (FR)...99 01034 --.

COLUMN 1:

Line 21, "to" should read -- too --.

COLUMN 2:

Line 20, "transmission)." should read -- transmission. --.

COLUMN 3:

Line 49, "stream" should read -- streams --.

COLUMN 4:

Line 57, "coding," should read -- coding, and --.

COLUMN 5:

Line 57, "of" should read -- of: --.

COLUMN 7:

Line 18, "data)," should read -- data), and --.

COLUMN 8:

Line 10, "involving" should read -- involving: --;

Line 25, "signal;" should read -- signal; and --;

Line 34, "radiofre-" should read -- radio fre- --;

Line 51, "rate;" should read -- rate; and --; and

Line 57, "radiofrequency" should read -- radio frequency --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 2 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13:

Line 42, "it is" should read -- are --.

COLUMN 14:

Line 50, "Clearly that" should read -- Clearly, --.

COLUMN 17:

Line 14, "simplifies" should be deleted; and

Line 21, "radiofrequency" should read -- radio frequency --.

COLUMN 19:

Line 3, "Time=[[t=]] t₁" should read -- Time=t₁ -- and

"Time=[[t=]] t₂," should read -- Time=t₂, --.

COLUMN 20:

Line 13, "embodiment the" should read -- embodiment of the --;

Line 35, "accordance" should read -- according --;

Line 60, "created" should read -- created: --; and

Line 61, ":" should be deleted.

COLUMN 21:

Lines 26 and 35, "in" should read -- of --; and

Line 46, "comprises" should read -- comprises: --.

COLUMN 23:

Line 7, "a" (second occurrence) should read -- as --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006



Staple
Here
Only!

PRINTER'S TRIM LINE

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 3 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 28:

Line 46, "FIG." should read -- (FIG. --.

COLUMN 29:

Line 47, "be" should read -- the --.

COLUMN 31:

Line 45, "the 501." should read -- the 501 --.

COLUMN 35:

Line 12, "with" should read -- which --.

COLUMN 36:

Line 17, "solutions" should read -- solutions: --.

COLUMN 37:

Line 23, "(eg" should read -- (e.g., --.

COLUMN 38:

Line 31, "changed. invention" should read -- changed. ¶ The scope of the present invention is not limited to the details of the forms of embodiment discussed above by way of example but extends, on the contrary, to changes within the grasp of a man of the art. It is clear, for example, that the invention --; and

Line 56, "sub-carriers" should read -- sub-carrier --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 4 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 39:

Line 9, "said" should be deleted;

Line 29, "comprising" should read -- comprising: --; and

Line 61, "signals," should read -- signals; --.

COLUMN 40:

Line 4, "read," should read -- read; --;

Line 7, "table," should read -- table; --;

Line 10, "signal," should read -- signal; --;

Line 12, "insetting" should read -- inserting --;

Line 13, "means," should read -- means; --;

Line 19, "means," should read -- means; and --;

Line 22, "wherein data" should read -- wherein said data --;

Line 53, "Method" should read -- A method --; and

Line 65, "important;" should read -- important; and --.

COLUMN 41:

Line 3, "important, transmitting" should read -- important; ¶ transmitting --;

Line 4, "radiofrequency" should read -- radio frequency --;

Line 6, "Method" should read -- A method --;

Line 9, "radiofrequency" should read -- radio frequency -- and "receiver," should read -- receiver; --;

Line 11, "data," should read -- data; --;

Line 21, "comprising" should read -- comprising: --;

Line 24, "radiofrequency" should read -- radio frequency --;

Line 25, "multi carrier" should read -- multi-carrier --;

Line 28, "bit" should read -- data --;

Line 29, "modulator," should read -- modulator; --; and

Line 46, "image" should read -- an image --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 5 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 42:

Line 1, "radiofrequency" should read -- radio frequency --;

Line 5, "rate," should read -- rate; --;

Line 6, "demodulator," should read -- demodulator; --;

Line 23, "radio" should be deleted; and

Line 44, "radio" should read -- the --.

COLUMN 43:

Line 6, "claim 46" should read -- claim 46, --;

Line 11, "channel," should read -- channel; and --; and

Line 44, "slip" should read -- step --.

COLUMN 44:

Lines 1, 7 and 30, "Method" should read -- A method --;

Line 3, "comprising," should read -- comprising --;

Line 34, "allocated" should be deleted;

Line 46, "wherein receiving" should read -- wherein the receiving --; and

Line 50, "are selecting" should read -- are selected in said selecting --.

COLUMN 45:

Line 3, "claim 75" should read -- claim 75, --;

Line 30, "channel," should read -- channel; --; and

Line 57, "channel," should read -- channel; and --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,120 B1

DATED : May 2, 2006

INVENTOR(S) : Francois Thoumy et al.

Page 6 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 46:

Line 31, "information," should read -- information; --;

Line 35, "acceptable" should read -- an acceptable --;

Line 54, "selected" should read -- selecting --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,120 B1

No. of add'l. copies
@ 30¢ per page

NOV 28 2006

